

S. S. "VICTORIEUX"

This vessel is at present under repair by the Rotterdam Dry Dock Co., and Mr. Paton of the Repairers has called at this Office and stated that difficulty being experienced in obtaining the .90 plates required the sheerstrake ~~which he stated had been discussed~~ with Mr. Leeuwenburg.

Mr. Paton submitted sketches showing a *he stated had been discussed with Mr. Leeuwenburg* proposal to fit the sheerstrake plates $5/8$ " in thickness with doubling plate $1/2$ " in thickness.

The sketches also show how it is proposed to fit the buttstraps to the sheerstrake and doubling.

It is submitted that the Repairers' proposal shown and amended on the sketches merit approval.

The sketches should be returned to the Rotterdam Surveyors.

19.3.20

Y 2 plans Rob

[Signature]
19-3-20
H. J.



© 2020

Lloyd's Register
Foundation

W783-0032