

1500,10,17.

1

S/S Lake City *Sunk by collision 18/19*

Sent to Chief Surveyors

6.12.17.

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S.

Side ~~Maibronk~~

Report

Cleveland

No. *115*

RIS

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

✱ 100A-1. (Steel)

1 DK (Steel)

Topside tanks.

Cell DB 20' 600'. Topside tanks 124 3306. F.P.T. 1806

FK 4BH. Can axep. P 115' F 26'. A.P.T. 506.

Merely affl.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register Foundation

W785-0015

" " " in engine and boiler space

Remainder in Holds.....

14.5

14.5

" Tie Plates, outside Hatchways.....

Deck * Material and thickness

Full page in RLB
inserted
copy RLB 29.4.18



© 2020

Lloyd's Register
Foundation