

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 18.7.1918 When handed in at Local Office 18.7.1918 Port of NEWPORT  
 No. in Reg. Book. 928 Survey held at NEWPORT MON Date, First Survey 9 Last Survey 16.7.1918  
 on the Wood, Iron or Steel S.S. 'Portugal' Master  
 TONNAGE:— Built at Hoboken By whom Chant. Nav. Anversois When 1909-6  
 GROSS 1463 Owners Armement Adolf Deppe Port belonging to Antwerp  
 UNDER DE. 1329 Owners' Address  
 NET 1070 (if not already recorded in Appendix to Register Book).  
 Surveyed Afloat or in Dry Dock? Name of Dock Alexandra Dk Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }  
 total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 30461 Port Hob

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	YEAR.	MONTH.
For Special Survey.		
Date of last Survey and of Periodical Surveys.		
Machinery and Boiler Surveys (including date of N.B., if any).		
+100A.1. Spar Dk. with		
fld. By 7.16		
S.S. Ant. no. 1-13.		
+LMC. M.S. 11-17		
B.S. 9-17		
N.T.S. 11-17.		

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR General examination - for deferring S.S. No. 2.

Decks, holds, peaks above tank, hatches, bridge space, windlass, steering gear etc., and machinery space now generally examined & found efficient.

Several hatch beam lugs in tween Dk. hatchways require to be repaired, which the supt states, will be done at the first opportunity.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								
PRESENT CONDITION OF THE								
Deck	good							
King of Decks								
Decks								
ways								
ings								
ns & Fastenings								
ide Plating	to water line							
king of ditto								
ts								
sthooks & Crutches								
soms								
res								
ree Frames								
ts								
sons								
Stringers	✓							
Inner Bottom Plating	✓							
State if Tanks have been examined inside	no							
State if Tanks now tested	no							
Bulkheads	good							
Ceiling								
Cement or Asphalt (State which.)	✓							
Rudder	✓							
Steering gear and its connections	good							
Windlass								
Have Pumps now been examined and found efficient?	no							
Have Sluice Valves now been examined and found efficient?	no							
Have Watertight Doors now been examined and found efficient?	no							
Dblg. Plates under Sounding Pipes	✓							
Engine Room Skylights	good							
Coal Bunkers, Open'gs, Lids, &c.								
Scuppers								
Cargo Hatchways								
Hatches								
Planking of Wood Vessels								
Caulking	ditto							
Treenails	ditto							
Breasthooks & Stemson	ditto							
Transoms, Pointers, & Crutches ditto								
Timbers of Frame at openings ditto								
Ditto ditto at other places ditto								
Stringers, Clamps & Shells	ditto							
Salting (State if examined.)	ditto							
Copper, or Y.M. of Wood Vessels (State if on Felt.)								
When put on, Month								
Boats	good							
Masts, Yards, &c.								
Condition, how ascertained	from Dk							
(State if ice-dges removed)	no							
Sails	✓							
Equipment letter	✓							
Anchors, No. of	3 B. 15. 1K.							
Cables (State if now ranged)	no							
length (on board)								
Rule length								
Hawser & Warps	good							
Standing & Running Rigging								

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel is now eligible to remain as classed with record of 'Examined 7.18', subject to repairs as above being carried out at first opportunity.

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) £

Rolling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Committee's Minute

Character Assigned

Fees applied for,

19

Received by me,

31.7.1918

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation

FRI 26 JUL 1918

Deferred for

Amis own

£4.4.4

Examined 7.18