

1

Sent to Chief Surveyors

23/9/08

Received from Chief Surveyors

VESSEL'S NAME

SS "Rinaldo"

Report

Sub

No. 15464

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee, the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Fuel tank

When due

+ 100 A 1 (Plat) Span deck

1 Dr (2d) & Span Dr (2d) & dup framing

NB. Cull DB a 126 u 6 x 13 H 0 f 170 1070c DTA 32 765t APT HSE

FK. SB to Span dr. 18H to Main dr. Cull Lloyd a 106 P 30 B 108 F H 1

RBN

C. A. D. 23/9/08



© 2019

Lloyd's Register
Foundation

W789-002