

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Date of last Survey and of Periodical Surveys. 9.38.

W79 - 0112

GLASGOW REPORT No 62115

Port of - Glasgow -

7. 2nd - 1940

Rpt. 14.

REPORT ON MASTS, SPARS, AND RIGGING.

Sir

Having, in accordance with your instructions, examined the Masts, Spars, Iron Work of same, and Rigging, of the Name of Vessel s/s "Scholar"

on the (Date of examination) 5th February 1940.

I have to report that I found

The Ironwork of Fore & Main Masts also their Top Mast's and Attachments under Hammer Test, in good condition.

- Rigging -

Fore Mast. Port side. 2 fore shrouds to Renew. Starboard side fore shroud to Renew. The Fore stay to Renew.

Main Mast. Port side fore shroud and Top Mast Back Stay to Renew. Main Mast. Starboard side fore shroud with its setting up screw to Renew.

Fee £ : :

- Main stay to Renew. - 2020

To the Surveyors,
Lloyd's Register of Shipping,

"all setting up screws with their Bolts & Shackles to be made workable."

parts affected, 1/3/40
George Sullerlin

as at present classed in the Register Book, with fresh record of survey 3, being examined next d...

board (if assign Ship and now whom? EY 2nd

now sa... has sa... ed, chy... in bea... y and... part n...

der for [Items: -

Copper, (Sta When fit Boats Masts, Condition (Stat Equipm Anchors Cables " " Chain Hawse Standi Seile

essel in tl remain

in on

100