



One propeller blade removed

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that this vessel is eligible to remain as CLASSET, without special restrictions on propellers & fittings.

24.10.02

*[Vertical handwritten notes in the left margin, including 'Propeller' and 'Fittings']*

*[Vertical handwritten notes in the middle margin, including 'Propeller' and 'Fittings']*

*[Vertical handwritten notes in the right margin, including 'Propeller' and 'Fittings']*

*[Vertical handwritten notes in the right margin, including 'Propeller' and 'Fittings']*

*[Vertical handwritten notes in the right margin, including 'Propeller' and 'Fittings']*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



©2020

Lloyd's Register Foundation