

(2m,11.5.)

1.

Sent to Chief Surveyors 18. 9. 06

Received from Chief Surveyors

VESSEL'S NAME *St. S. S. "Queen"*

Report *Eur* No. 14830

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*First entry*

When due

+ 100 A1 ("Steel")

1 DR (St) & span DR (1st line & 1st St) & deep framing

W. B = All DB a 126' u E & B 38' f 172' 10465 FPT 1225 APT 1275

PK 6BH Cum. Lloyd's A & CP P40' B240' F 37'

*C. H. P.*  
*18/9/06*



© 2019

Lloyd's Register  
Foundation

PILLARS, In tween Deck, size and spacing

24	48	24	48
34	48	34	48

Hold INC<sup>2</sup> AT ENDS.

Angle on ditto  
Tie Plate  
Deck, Material and thickness  
STEEL DECK  
RA SHEATHING