


It is submitted that in view of the state of  
ress of this vessel, as reported by the Society's  
eyors at Newcastle, the usual <sup>provisional</sup> certificates could not at  
ent be issued, but reports might be furnished on special  
ge survey report forms (Form 10) stating the actual present  
e of construction of both hull and machinery.

BH



25. 5. 23.

©

CW

WLL

Lloyd's Register  
Foundation

W8-0163