





London

(2)

Sp' Port Campbell Cond

holds to be tested, and hand pumps to examine

owing to urgent demand for vessel to sail the owners regret being unable to complete the survey on this occasion, it is expected to be able to complete the survey on vessel's return to N.R.

General Examination:- In view of the fact that the year of grace has expired, the vessel has been examined afloat as far as practicable lower holds and twin decks, Engine & Boiler spaces, Twin deck Bunkers, Mast & Spar rigging, Decks, which for TE Examd. and found in good order. I am of opinion that the condition of this vessel merits the record Examined 3.18. if desired

GJR

Sank under  
Boiler in  
Mch 1916



© 2020

Lloyd's Register  
Foundation

W803-0041 2