

Bel. 6625.

TSS. Otranto

It is submitted this case be referred to the London Surveyors for completion. & it is also submitted that the Belfast Surveyors be requested to state whether the thickness of the lower front end plates of the single ended main boilers should not be 1" thick as shown on the approved plan, & not $\frac{15}{16}$ " as given in their report.

DRK

#42.

9-7-09

9-7-09

cc:- 9/7/09



© 2021

Lloyd's Register
Foundation

W806-0049