

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

17th July, 1914.

Dear Sir,

Reverting to my letter of the 13th and yours of the 26th May last respecting the steam trawler "ONWARD HO", I have now to acquaint you that the Committee have had before them a report from the Society's Surveyor at Monte Video from which it would appear that temporary repairs on account of stranding have been effected to the vessel's shell plating &c. at that port. The Surveyor recommends that the steamer should be dry docked for permanent repairs and her machinery opened out for examination upon her arrival at Vancouver, and I shall therefore be glad if you will give the case the necessary attention.

Extract from Monte Video report:- "Found one shell plate in B strake and one shell plate in C strake, starboard, slightly set up in frame spaces 2 to 5 inclusive forward of stokehold bulkhead. Five frames immediately forward of stokehold bulkhead, set up, two wash plate stanchions buckled and two rivets started and weeping in 3rd and 5th frames starboard forward of stokehold bulkhead."

I am, Dear Sir,
Yours faithfully,

Secretary.

T.G. Mitchell, Esq.,

VANCOUVER, B.C.

© 2021

Lloyd's Register
Foundation

W808-0158