

Received by Chief Ship Surveyor 17.5.16

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. Pearl*Rpt. *Hul*No. *29304*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

## DAMAGE.

Damage through being struck by another vessels while lying aground.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	3	1			1	1	1
Removed and faired or repaired.....	1	-			1	1	1
Faired or repaired in place.....	1	1			3	-	-

Other items:-

Vessel examined in Dry Dock. Bottom Cleaned and Coated.  
Gudgeons rebushed. Bulwark plating, Rail & Stanchions  
repaired as necessary.  
Minor repairs effected.

Wear & Tear:- One Hawse Pipe renewed. Windlass renewed. Two new lengths of Cable  
of required weight & test now placed on board. Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with

record of Survey 5-'16 as recommended

100 A.1.

5-'16 *Hul* 600.

© 2021

Lloyd's Register  
Foundation