

S. S. " P O L A M H A L L " .

A report has now been received from the Surveyor appointed by Lloyd's Agent at Port Said from which it appears that two furnaces of the starboard Boiler have come down to a serious extent due to shortness of water in the Boiler.

The Surveyor recommended the vessel to proceed to Alexandria where temporary repairs were to be carried out in order that the vessel might continue her voyage. A telegram has since been received from the Alexandria Surveyor asking whether the vessel can proceed home with one Boiler only. The Owners have been communicated with and they have given instructions that complete Boiler repairs are to be carried out at Alexandria and Lloyd's Certificate of seaworthiness should be obtained before the vessel proceeds on her voyage home.

It is submitted that action should be deferred pending the report of the Alexandria Surveyor.



58292
© 2021

Lloyd's Register
Foundation