

Chief Surveyors _____

Received from Chief Surveyors _____

L'S NAME SCOTTISH MAIDEN Report Liv No. 113988

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey Damage When due -

Subject to indentified Nos 4 & 5 ^{main} sheerstrake plates from aft (P.S.)
being permanently repaired at Owners convenience & a bowser
over & 2 lengths of chain cable being supplied at end of
present emergency.

CLS
8-4-60

States
note
ful.

^{other}
without a special condition.



© 2021

Lloyd's Register
Foundation

W81-0010

Recent