

M.V. "SCOTTISH MAIDEN"

Amsterdam report-15681A

Port side

Crankshaft	Lloyd's No. 1099	JS 8-12-38 (fore & aft).
Thrustshaft	Lloyd's No. 5707	HPB 3- 2-39
Interm. shaft	Lloyd's No. 5897	HPB 31- 3-39
Screwshaft	Lloyd's No. 5749	HPB/KK 21-3-39

Starboard side

Crankshaft	Lloyd's No. 1097	JS 26-11-38 (fore)
	Lloyd's No. 5382	HPB 9-11-38 (aft)
Thrustshaft	Lloyd's No. 5708	HPB 3- 2-39
Interm. shaft	Lloyd's No. 5901	HPB 3- 4-39
Screwshaft	Lloyd's No. 5748	HPB/KK 21-3-39

[Signature]



© 2021

Lloyd's Register
Foundation

W81-0023