

F.E.

Received by Chief Ship Surveyor 3/10/11

Received from Chief Ship Surveyor _____

VESSEL'S NAME H H Prignton

Rpt. Sea

No. 25038

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 61.00

Depth "d" 17.75

Framing: Table No. 3 page 11

Description Bulk angle, as approved

Longitudinal No. 17049

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.46}{17.75}$

Upper Deck Sheerstrake ☒

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **+** 100A-1. (Std) as recommended.

+ 100A-1 (Std)

1st (Std)

WB: bell DBa 94 n 3436 f104 H90E FRT114L ART114L
FK. HBA. Cam. Lloyd UV 00 P29 B54 F25



© 2004

Lloyd's Register
Foundation

W916-0036