

S.S. "OHIO".

It is submitted the Nantes Surveyor should be asked whether he can give the actual diameter of the propeller fitted in this vessel.

In the First Entry Report it is given as 5<sup>m</sup>600. In reply to enquiry the Havre Surveyor states he is informed by the Director of the Chantiers de Normandie that the diameter is 5<sup>m</sup>400.

On the approved plan of the shafting the diameter of the propeller is given as 5<sup>m</sup>000. With a screw shaft 380 m/m diameter, the diameter of the propeller should not exceed 5<sup>m</sup>200 to meet the requirements of the Rules.

ARR

18.2.15.

Li:- 18/2/15



© 2020

Lloyd's Register  
Foundation

W819-0061

W819-0062 1/2