

Lloyd's Register of British & Foreign Shipping,

201, Tower Building,

Liverpool, 8th. January. 1913.

LOYD'S REGISTER
LONDON
REC- 9 JAN 1913
ANS^D

Sir.

In reply to the Secretary's letter S.6/1/13, I have to state that the cable holders are not yet satisfactory and are again being changed. The Owners Superintendent very definitely states that he does not want any but the full classification certificate.

I have again to-day urged the builders to range the cables so that the variations of the links may be more accurately gauged and have suggested that the makers of the windlass, who are stated to have made the cable holders to their own design, should obtain cable holders from some standard maker.

I am, Sir.

Your obedient Servant.

Wm. Williamson

R. Williamson Esq.

LIVERPOOL.



© 2019

Lloyd's Register
Foundation

W82-0121

Spacing

BEAMS, Third and Fourth Deck, Single Angle,

Bulkhead Plate, T. D.

Deck Material thickness

Poop Deck Stringer Plate, breadth & thickness

Lloyd's Register of British & Foreign Shipping

201 Tower Building
Liverpool, 8th January 1913.

Sir,

In reply to the Secretary's letter 2.6/13. I have to state that the cable holders are not yet satisfactory and are again being changed. The Owners Superintendent very definitely states that he does not want any but the Hill classification.

I have again to-day urged the builders to range the cables so that the variations of the links may be more accurately gauged and have suggested that the makers of the winches, who are stated to have made the cable holders to their own design, should obtain cable holders from some standard maker.

I am, Sir,

Your obedient servant,

Wm. W. ...
+ *Wm. W. ...*
As holder

Referred to the Cable Test ...

W. W. ...
LIVERPOOL.

© 2019



Lloyd's Register
Foundation

BEAMS, Third a
Bulb A
Angles
Spacing
BEAMS, B