

GOVERNMENT SERVICE.

1

Received by Chief Ship Surveyor 25.1.16Received from Chief Ship Surveyor 25 JAN 1916VESSEL'S NAME Shelss Lord Roberts Rpt. Shel No. 29086

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

whirl on Admiralty Service

now repaired as follows:-

P.S. done 4.15

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....	2						
Faired or repaired in place.....		4					

Other items:-

Minor repairs

Nothing has been done in regard to the S.S. No 2
due 8.15 as the vessel is still on Government Service.

It is submitted the vessel is worthy to remain as classed with

~~record of Survey~~~~as recommended~~~~action be deferred~~for the present.© 2021
25.1.16Lloyd's Register
Foundation

W826-0008