

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19.9.10 When handed in at Local Office 21/9/10 Port of GRIMSBY
No. in Survey held at GRIMSBY Date, First Survey 12/9/10 Last Survey 14/9/1910
Reg. Book. on the Wood, Iron or Steel Sec. K. BEREIAN. (No. of Vessel) two Master D. Berndtsson

TONNAGE:— Built at Selby By whom Cochrane & Son No. 467 When 1910
GROSS 221.13 Owners St. Central Co-operative Eng. Ship Repairing Co. Ltd. Port belonging to Grimby
UNDER DK. 197.25 Owners' Address _____
NET 101.63 (If not already recorded in Appendix to Register Book.)

Official No. 127868 Name of Dock Alexandra St. Destined Voyage Fishing
Surveyed Afloat or in Dry Dock? _____

WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
total capacity tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. _____ Port _____
Class Contemplated _____
Society's Freeboard (if assigned) as painted on Ship and now verified _____

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? _____ Was a damage report made by anyone else? If so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of 1st Entry Report.

After the engines & boiler had been shipped, the deck & casing were closed in and efficiently rivetted up. Storm covers fitted hinged to fiddley hatches.

SUMMARY OF DAMAGE REPAIRS —	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (state which)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Roofing	Ceiling	Sails
Rivets	Steering gear and its connections	Treenails	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson	anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length size (on board)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Rule length size (per Table 23)
Floors		Stringers, Clamps & Shells ditto	Hawser & Warps
Keelsons		Salting (State if examined.) ditto	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,09," or "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and pEND09, &c."


This report is forwarded for the information of the Committee.

Survey Fee (per Section 28)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 28)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

W. H. Aspinall
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____
Character Assigned See minute on F. E. Rpt
Hul 22971

FRI. 23 SEP 1910



10m. 99.—Transferor Int. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

No Certificate required if so, to be sent to