

SAT 3 JUL 1916

No. 75077

## REPORT of SURVEY for REPAIRS, &amp;c.

- 6 JUL 1916

When handed in at Local Office

- 6 JUL 1916

Port of

LIVERPOOL

Date of writing Report.

When handed in at Local Office

6 JUL 1916

No. in Reg. Book. Survey held at Birkenhead. Date, First Survey 9 (No. of Visits) Last Survey June 29 1916  
 205 on the Wood, Iron or Steel at Malakand. Master Montador  
 TONNAGE: Built at Belfast By whom Hasland + Wolff. Lt When 1905-12  
 GROSS 1653 Owners J. F. Brocklebank & Co. Port belonging to Liverpool.  
 UNDER DEK. 1320  
 NET 1428  
 Owners' Address 141 LAIN (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? D.D.K. Name of Dock Bkw. D.D.K. Destined Voyage Calcutta

WB=Cell DBor DBa feet; uEgB feet; f feet; t tons; FPT tons; APT tons; MT feet tons.

N.B.-All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3556 Port Cal.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER,  
X for Special Survey,  
Date of last Survey and of  
Periodical Surveys.Years  
since  
last  
Survey  
Machinery and Boiler  
Surveys  
(including date of N.B., if any).

E100A1-7.15.

E100A1-  
May 13.

May 13.

May 13.

E100A1-2.14.

Society's Freeboard (if assigned) as  
painted on Ship and now verified

ft... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking.

Vessel examined in drydock, bottom cleaned & recoated, rudder lifted, bottom pintle renewed & top refitted. The port bilge keel is bent down somewhat, vessel efficiency is not affected.

SUMMARY OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE								
Decks	good							
Caulking of Decks	"							
Watervays	"							
Coamings	"							
Beams & Fastenings	good							
Outside Plating	"							
Caulking of ditto	"							
Rivets	"							
Breasthooks & Crutches	"							
Transoms	"							
Frames	"							
Reverse Frames	"							
Floors	"							
Keelsons	"							
Stringers								
Inner Bottom Plating								
State if Tanks have been examined inside								
State if Tanks now tested								
Bulkheads								
Ceiling								
Cement or asphalt (where white.)	good							
Rudder								
Steering gear and its connections								
Windlass								
Have Pumps now been examined and found efficient?	"							
Have Safety Valves now been examined and found efficient?	"							
Have Watertight Doors now been examined and found efficient?	"							
Bracing, Plates under Sounding Pipes								
Engine Room Skylights								
Coal Bunkers, Open'gs, Lids, &c.								
Scuppers								
Gage Hatchways								
Hatches								
Planking of Wood Vessels								
Caulking	ditto							
Treenails	ditto							
Breasthooks & Stemson	ditto							
Transoms, Pointers, & Crutches	ditto							
Timbers of Frame & Openings	ditto							
Ditto ditto at other places	ditto							
Stringers, Clamps & Shells	ditto							
Salting (State if examined)	ditto							
Copper, or T.M. of Wood Vessels (State if on Paint.) When put on, Month Year								
Boats	good							
Masts, Yards, &c.	"							
Condition, how ascertained (State if wedges removed)	Good deck							
Sails								
Equipment letter C+								
Anchors, No. of 3100d16								
Cables (State if now ranged) No								
length (on board) Rule length size								
Rule length size								
Hoists & Warps	good							
Standing & Running Rigging	"							

## General Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-15," or "to remain as classed and to have record of survey, 1-15, and the notations of "No. 1-15 and ptno 15, &c."

This vessel as far as seen is in good and efficient condition & eligible to remain as classed & to have fresh record of survey 1-16. Bkw.

100.115 - Transfer to write on or above the space for Committee's Minute.

Survey Fee (per Section 88) £ : :

Special Damage or Repair Fee (if any) £ : :

Travelling Expenses (if chargeable) £ : :

Second Surveyor's Fee (if any) £ : :

Fees applied for.

Received by me,

19

a. g. Barrett,  
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

100.115 record 6.16

To Certificates required p. 76, to be sent to

W839-0060

Lloyd's Register  
Foundation