

1

fuss hd.

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel Screw "SIMNIA" Report Gls. No. 56980**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

- ✓ \*100A1 'Carrying Petroleum in bulk'
- ✓ 1 Dk. 2nd Dk. clear of cargo tanks 'Longitudinal framing at bottom and at deck'
- ✓ Cell. DBuE 66' 134t, DTf 25' 265t, FPT 104t, APT 60t.
- ✓ FK, 16 BH, Lloyd's A & CP.
- ✓ P 91', B 41', F 48'
- ✓ Machy. aft.

This ship is ~~affiliated~~ to the "STANDELLA"  
a sister vessel



2020  
28.5.36

Lloyd's Register  
Foundation

W84-0074