

F.E.

Stancor

Received by Chief Ship Surveyor 23.8.04

Received from Chief Ship Surveyor

VESSEL'S NAME S. S. "Cherrybrook"

Report Mdb No. 3942

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

| Items.  | Additions (if any) required by Rules, or as approved. | On account of:— |
|---|---|-----------------|
| Main Sheerstrake . .  | to 20"  | proportions     |
| Spar Sheerstrake . .  | ✓   | ✓               |
| Description of Framing:— Deep (bulb angle) framing, as approved (viz., ordinary, deep, zed, channel or bulb-angle). |   |                 |

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100 A1 ("Steel") as recommended.

$\pm$  100 A1 ("Steel")

1 Dk (Stl) & deep framing. Well deck.

WD = DBa 40' All DBu E 15' DBu B 16' f 83' 190t F'PT 23t APT 19t

FK. 4 BH. Cem. Lloyds A & CP.

Q 97' B 17' F 21'

J. H. T.  
23/8/04.



© 2020

Lloyd's Register Foundation

W84-0164

W84-0166

50,44