

GOVERNMENT SERVICE.

Received by Chief Ship Surveyor 3.9.15

Received from Chief Ship Surveyor

SEP 1915

VESSEL'S NAME Stl. T.S.S. "MARERE".

Rpt. Syd.

No. 5054

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Com'n *1st S.S. No. 3 due 12. 14 10 Child*

The 1st S.S.No.3 which became due 12. 14 was partly held at London in May last.

Some shell plating requires to be repaired.

The London Surveyors stated in May last that the vessel was on Admiralty service.

The Sydney Surveyors now report the vessel has been placed in dry dock, the bottom cleaned and coated.

The indented plates etc, have been examined and found sound.

The master stated that the necessary repairs and the Special Survey No.3 would be attended to at a home port.

The vessel now trooping.

It is submitted action be deferred.

M *1st S.S. No. 3* *15*
4.9.



© 2020

Lloyd's Register
Foundation