





The first bowee anchor and 15 fms of chain cable were lost at this time, new anchor & cable has been ordered and up to time of vessel sailing not delivered. The Owners Supt states he will inform us where the new anchor & cable will be placed on board.

General Examination The holds, bunkers, engine & boiler spaces examined, decks, hatchways, casings, steering engine and gear examined, Ventilators & rigging examined  
Repairs a number of hatches renewed, steering engine piston rings & valve spindles renewed, the galley top which was cracked & part renewed, defective hold ceiling renewed,

The Owners Supt wishes the examination of the bottom and rudder & ballast tank or to be taken as part of the Special Survey.

Special Survey  
To complete the Special Survey at some convenient opportunity, all the Rule requirements to be complied with except the examination of the Bottom, rudder & ballast tanks & WINDL

## ANCHORS.

[illegible]

## CHAIN CABLES.

[illegible]

Iron Stream Chain }  
or Steel Wire.... }