

Chief Surveyors 16-8-'16

Received from Chief Surveyors

NAME Steel S. S. "Matheran"

Report Gb.

No. 36228

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey Damage & Completion of 1st S.S. No. 2 When due 5-'11

notes.

The Class of this vessel is subject to the Rudder Pintles being rebushed at next Dry Docking.

M

18-8-'16



© 2020

Lloyd's Register
Foundation

W849-0084