



LLOYD'S REGISTER
LONDON. 342, Argyle Street, Glasgow

It is submitted the Secretary of the Admiralty should be informed, in reply to his letter of the 19th ultimo, that there is no standard method for securing piston rod nuts, and various methods have been adopted by different Engineering Firms.

Messrs. Earle's Shipbuilding & Engineering Co. Ltd.'s practice is the same as adopted by some other Firms and has been accepted by this Society.

Lr: - 8/10/18



© 2020
ASR

7.8.18.

Lloyd's Register
Foundation
W85-0126