

If the vessel has water Ballast Tanks, state whether the ... of the tanks ... girders.

Las

(WRECK Box 100)

W-28B

1

Received by Chief Ship Surveyor 23.7.15

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. Monitoria Rpt. Cff No. 37861

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through Collisions

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed.....							
Removed and faired or repaired.....	3						
Faired or repaired in place.....	3	4					

Other items:-

Diesel examined in dry dock - bottom cleared & coated. minor repairs effected.

It is submitted the vessel is worthy to remain as classed with record of Survey 7.15 as recommended


100 A.1.

7.15 Cff

as to

ommendation, &c.:- This

Classification is su... classification to... existing classification and notification of the vessel in the Reg... Book without fresh record of Survey," "to remain as cla... ss No. 1-11 and ptND11, &c."



in my opinion The Register Book Foundation

100-0101

Equipment le... Anchors, No... Cables (state... length... Rule les... Hawser & W... Standing & T...