

ANSO

uck h

Chief Surveyors 4. 10. 18

Received from Chief Surveyors

S NAME Stl. Sc. K. "NJORDUR". Report Liv. No 18197

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Survey S.S.No.1 When due 10. 16.

Noted.

4. 10. 18

The Surveyors should be requested to state whether they are correct in reporting that the vessel has only 90 fathoms of  $1\frac{15}{16}$  chain cable on board, in view of the fact that she was originally supplied with & still requires 105 fathoms of  $1\frac{1}{16}$

W852-0123

7-18