

# Lloyd's Register of Shipping

1965 C.F. No. 3992

1,809,70,37.

th Jan 191  
Rudder

ent to Chief Surveyors 25. 7. 18

Received from Chief Surveyors

26 JUL 1918

ESSEL'S NAME Stl. S.S. "MESSIDOR".

Report Mch. No. 4139

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

~~S. 8. No. 3~~

When due

~~12. 15.~~

18P. 195. 2


720 P45  
CONF.

The class of this vessel is subject to the mast wedges being removed for examination of masts in way of same.

In reply to enquiry the Manchester Surveyors state that there are no mast wedges in way of the decks, the masts being secured by angle rings.

It is submitted the vessel appears worthy to remain as classed, without fresh record of survey; without special condition.

*As now, Without  
etc.*



26. 7. 18

© 2021

Lloyd's Register  
Foundation

W853-0127

consequen  
o have re

No 3-7-18.