

LOYDS REGISTER

LONDON

14 OCT 1913

ANS

Confirmation of Telegram

J. R. Apple

AND
Messrs Lloyds Register of British

& Foreign Shipping,

Hull

13th. October. 1913. 71 Fenchurch St,
London.E.C.

Sent 12-15. p.m. Earle's Steamer "New Sweden" result colliding
dock wall slightly bent stem two bow plates indented,
rivetting and caulking made good vessel seaworthy. Owner
Mr. Brostrom now here requires delivery of vessel to-morrow
to proceed load at Lulea which port likely to be frozen up,
if vessel detained here desires classification certificates
proposes making permanent repairs say 2 month's time.
Wire instructions.

Recd. 4-45. p.m. "New-Sweden" provided temporary repairs
carried out satisfaction Societies Surveyors before vessel
sails she can be classed subject to permanent repairs
being effected and certificate of Classification can be
issued endorsed to this effect.

FOR EARLE'S
SHIPBUILDING & ENGINEERING CO. LIMITED.

Homans
MANAGER



© 2020

Lloyd's Register
Foundation

W854-0040

OCT 14 1913

~~16.10.13~~

© 2020

Lloyd's Register
Foundation