

**COPY.**  
**Lloyd's Register of Shipping,**

71, Fenchurch Street, E.C.

2nd June 1915.

Dear Sirs,

I have to acquaint you that it appears from a report received from the Surveyors at Liverpool on the steamer "MENDIBIL MENDI" that several bottom plates in the after body and on the starboard bilge aft are indented and the Surveyors recommend that repairs should be effected at the Owners' convenience.

The survey of the machinery was also partly carried out and to complete the same the H. and I.P. cylinders and pistons, all slide valves, tunnel and crank shafts (except H.P.pin), air, bilge and auxiliary pumps, condenser and pumping arrangements require to be examined. It is understood that the Special Survey No.3 will be carried out at Bilbao at an early date and I have therefore to request that you will give the case the necessary attention in due course.

I am, Dear Sirs,

Yours faithfully,

The Surveyors,  
Bilbao.

Secretary.

© 2020  
Lloyd's Register  
Foundation

W854-0092