

to Chief Surveyors 30-10-14

Received from Chief Surveyors

SEL'S NAME Steel S.S. "Hungerford"

Report Phb.

No. 2649.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey Damage & alterations for carriage of oil fuel in D.B. When due (1st S.S. no. 1, due March '14).

Notes:

Permanent repairs to shell plating, framing etc to be effected
Nothing has yet been done towards the 1st special survey no. 1, due 3-17.

The notation of "carrying oil fuel in double bottom tanks" in Column 3) should be subject to all of the requirements of the Specification being complied with.

