

Memo. respecting incomplete survey on  
the *M/V. Surat*

London 20 - 1 - 19 41

In reference to London report N° 108919  
N° 3 centre crank pin and N° 4 side rod crank  
pins were examined

*Noted  
30/1/41*

*RW Coomber*

Surveyor.

FOR { MR. HILL.  
MR. NETTLETON.



© 2020

Lloyd's Register  
Foundation.

W86-0001