

1

Free Board

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Single Screw M.V. "SURAT" Report Gl.s. No. 60460**For the CHIEF SHIP SURVEYOR ~~OR CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

FIRST ENTRY.When dueTonnage Opening Fitted.

100A1 "With Freeboard"

2 Dks. and Shelter Dk.

Cell.DB 377' 1413t, MT 23' 978t, FPT 141t, APT 219t.

FK, 7BH(Coll.BH to Shltr.dk., 6BH to 2nd Dk.) pt.cem., Lloyd's A &amp; CP.

F 38'

O.L.459.5'

E.S.D.

*J. H. J.*  
*12.1.39.*



© 2020

Lloyd's Register  
Foundation

W86-010