

Official No. *WRECK BOX*
 Register Tonnage *20 (207)*
 If Surveyed while Building, Afloat, or in Dry Dock *Building*
 Register Tonnage, as a Steamer
 cut on the Beam
 Length *20* Feet *6* Inches
 Breadth Outside *20* Feet *6* Inches
 Depth of Hold *12* Feet *2* Inches
 No. of Decks with Flat laid *One*
Two

Extract of letter No.5134/23.A, dated 9th.August 1913, from
 Mr. C. J. Homer, Executive Engineer, Lighthouse Division,
 to Messrs: A.C. Martin & Coy - Rangoon.

" With reference to your letter No.II-484/19 of the 1st.
 Instant, I have the honour to inform you that the Boiler in question
 was obtained for this Department by the Director-General of Stores,
 London, who did not furnish the Maker's Certificate for the Boiler
 and in fact, as far as this Department is concerned, such certifi-
 - cate is hardly necessary as it is part of the duties of the
 Director-General of Stores to satisfy himself that all supplies by
 made by him are tested in accordance with rules and specifications
 before despatch to the East.

A blue print of the drawing of the Boiler to-gather with
 all necessary information about it as to steam pressure etc, as
 furnished to this Department by the India Office, was sent to you by
 the Subdivisional Officer, Lighthouse Subdivision with his letter
 No.1843, dated the 23rd.July 1913, and was acknowledged by you in
 your letter No.II-449/19 dated the 23rd.July 1913. This is the only
 information I can give you about the Boiler and it is
 is necessary.

I have been in communication with the Secretary
 Boiler Commission, who informs me that all you have to do
 to him to have the Boiler tested under section 20 of the
 and Prime Mover's Act 1910, with a fee, payable in adv
 and that he will then arrange to have the Boiler te
 Grant you the necessary certificate.

I send for your information copy of a l
 enclosure from the Superintending Engineer, Marit

Register

depth 17-1

THICKNESS.

lip.	Per Rule or as Approved.
4	8x4
12	12x12
4	8x4
4	8x4
	8x8
	8x8
	6x8
	2x12
	2x12
	Size required per ft.
	1/2
	1/2
	1/2
	1/2
	1/2
	5/8
	1/2
	Inches
	upwards,
	Gunwale
	thickness not
	of the chock



© 2020
 Lloyd's Register
 Foundation

W860-0069 1/2

W860-0069 1/2

- 2 -

regard to the cost of a new Boiler to replace the one sold to you
from which it will be seen that an Indent for the new Boiler has
already been sent to the Director-General of Stores, London. "

X

X

X

X

X

X



© 2020

Lloyd's Register

W860-00692