

Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

NAME WOOD S. "HYASTAN"

Rpt. Rangoon

No. 319

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

vey \_\_\_\_\_

First Entry

The Superintendent at Lloyd's Proving House, Cradley Heath,  
and be requested to forward particulars of chain cable certificates  
22689, 26685, 26920 & 26932.

10.11.19

M acc.  
20  
12-11-19



© 2020

Lloyd's Register  
W860-0086