

COPY.

WRECK BOX

No.

20787

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

21st June, 1918.

Dear Sirs,

S. With reference to the classification in this Society's Register Book of your steamer "HURUNUI", I beg to acquaint you that the Committee have had before them a report of a survey held on the vessel at Christchurch, New Zealand, from which it appears that temporary repairs have been effected in way of some leaky frame rivets on the port side of No.1 hold.

It is recommended that the defective rivets should be renewed and a thorough examination made in the vicinity of the same, at the first dry docking of the steamer.

I am, Dear Sirs,

Yours faithfully,

Secretary.

Messrs. The New Zealand Shipping Co., Ltd.,  
Rochester Building,  
138, Leadenhall Street,  
E.C.3.



© 2020

Lloyd's Register

Foundation

W8600047