

Chief Ship Surveyor

7/2/12

Received from Chief Ship Surveyor

SHIP'S NAME

H. H. Hurumi

Rpt.

Grk

No.

16169

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

## DAMAGE.

Damage through

fire striking a dock wall at Eran

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	10		5		57	9	74
Removed and faired or repaired .....	1						
Faired or repaired in place .....	2	1					

Other items:-

the bulkhead between Nos 1 & 2 holds partly  
ruined, the jellies & girders in No 1 hold & part  
of those in the tween decks ruined & minor repairs  
done.

As submitted the vessel is worthy to <sup>be</sup> ~~remain~~ as classed ~~with~~

Record of Survey <sup>as</sup> ~~has been~~ per endorsement on  
the 1<sup>st</sup> entry report.



© 2020

Lloyd's Register

W860-0120