

Engine Ro  
Gross Ton  
Less Crew S  
Less above C  
Fumina Ro

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES { 1363 } RECTOR  
{ 1364 }

LLOYD'S REGISTER OF SHIPPING,  
17 BATTERY PLACE,

LLOYD'S REGISTER  
LONDON.

NEW YORK

May 10, 1917.

REC'D MAY 15 1917  
AN

Dear Mr. Scott;

With reference to your letter of the 2d ultimo and to the case of the steamer "MIELERO"-Boston Report No.899-I enclose herewith a letter received from the Surveyors from which it will be seen that the cellular double bottom in way of the engines and boilers of this vessel is not cemented but coated with a Bituminous Composition.

Yours faithfully,

*R. P. Hutchinson*

Andrew Scott, Esq.,

LONDON.

Encl.



© 2020

Lloyd's Register  
Foundation



Referred to the Chief Ship Surveyor.

*al*  
MAY 25 1917

Also for Mr. S. A. Hill to note.

*M*  
*25 57*



© 2020

Lloyd's Register  
Foundation

Do, under crown of  
Engine Room ...  
Gross Tonnage  
Less Crew Space  
Less above Crown of  
Funnel Room  
GRAMS