

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 2/1/12 When handed in at Local Office 2/1/12 Port of HullNo. in Reg. Book. 1586 Survey held at Hull Date, First Survey 4 Last Survey Dec 28th 1911on the Wood, Iron or Steel St. K. MYTON MasterTONNAGE:— Built at Hull By whom Charles Lee Ltd. When 1906 MONTH 11GROSS 289 Owners City Steam Fishing Co. Ltd. Port belonging to HullUNDER DEK. 256 Owners' AddressNET 114 (if not already recorded in Appendix to Register Book)Surveyed Afloat or in Dry Dock? Name of Dock St. Andrews Destined Voyage FishingWB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.Last Report, No. 24307 Port Hull

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs in account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion S.S. N°1. (see Hull report N° 23914)was placed upon the slipway. Bottom & under cleaned, examined, & treated. Two in order.
Repairs:— 2 new under plates fitted & a few small rivets removed.Comp. S.S. N°1.
Side bumpers cleaned, examined, found good & treated - no welding.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Paired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalte (State which.)	Rudder	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Plating under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Caulking	Treenails	Breasthooks & Stemson	Transoms, Painters, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shells	Salting (State if examined.)
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

Copper, or P.M. of Wood Vessels (State if on Feet.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed)	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length	size	Rule length	size	Hawser & Warps	Standing & Running Rigging
Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of ss No. 1-10 and ptnD10, &c."

This vessel now appears to be in good condition, is eligible in my opinion to remain as classed & to have record of survey 12.11 & the notation of S.S. Hull N° 1-11 in the Register Book as recommended in Hull report N° 23914.

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) £

Traveling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

FRI. JAN 5 - 1912

Character Assigned

1000
Stm Trawler
S.S. N° 1-11

© 2020

Lloyd's Register Foundation

W863-0086