

F.E.

Received by Chief Ship Surveyor 28/1/06

Received from Chief Ship Surveyor

VESSEL'S NAME *Sat. S. Trawler "Bryton"* Rpt. *Atl* No. *18539*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>10' 1/16 in lieu of 8"</i>	<i>not required</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Ordinary, of increased scantlings to compensate for omission of usual frames.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ 100A1 (Shul) Steam Trawler as recommended.

+ 100A1 (Shul) Steam Trawler
10x

B.H. 8' H B.H. 6mm, Lloyd's 200.P 270' 720'

RLB
28/1/06



© 2020

Lloyd's Register Foundation

WEB FRAMES, In Fore Body, No. and Spacing
" " " Brdth. & Thickness
" No. of Side Stringers " "

Deck, Material and thickness *Steel*
* If Iron or Steel Deck, state if whole or part, and if wood deck

BULKHEADS. Number. Thickness. Horizontal. STIFFENERS