

118.

to Chief Surveyors 3. 5. 19.

Received from Chief Surveyors

SEL'S NAME Steel S.S. "MUNISLA". Report Pca. No.16

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/593.)

ure of Survey Grounding. When due

Subject:-

Indented top side plating to be dealt with at the Owners' convenience.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

before the casualty occurred.



© 2020

Lloyd's Register Foundation

W863-0100

6. 5. 19.

ser & Warps
ding & Running Rigging

Vessels...
G
H
g
H
aged)
ted
Loo