

Received by Chief Ship Surveyor 11-3-15

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. Hartdale Rpt. Gls No. 34917

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Compl S.S. No. 1 AND DAMAGE.

Damage through striking dock wall (see Riv rpt 71860)


now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....	1						
Other items:-	Vessel examined in drydock minor repairs effected.						

The 1st S.S. No. 1 has also been ^{completed} ~~held~~ and following repairs done due to wear and tear:-
Bottom cleaned & coated
Rudder rebushed.

It is submitted the vessel is worthy to remain classed with record of Survey 315 Gls and notation of SS Bkn No 1.14 as recommended.

100 A.I.
3.15 Gls
S. S. Bkn No 1.14.



10m. 2.14. -
Special
Traveller