

Date of writing Report 11/2/18 to 11/2/18 When handed in at Local Office 11/2/18 Port of Hull.  
No. in Reg. Book. 265 Survey held at Hull Date, First Survey 3/1/18 Last Survey 9/2/18  
265 on the ~~Wood, Iron or Steel~~ SC SR. HARROGATE (No. of Visits 3) Master

No. in Reg. Book. *265* Survey held at *Full* Date, First Survey *3/1/18* Last Survey *9/2/19*  
 on the ~~Wood, Iron or Steel~~ *SC SR. HARROGATE* (No. of Visits *3*) Master

TONNAGE:-	Built at	By whom	YEAR.	MONTH.
GROSS 1168	Hull.	Charles C. L.	When 1911-	9.
UNDER DK. 933	Owners	Wilson & R. E. Rhy Shipping Co. L.	Port belonging to	Hull.
NET 472	Owners' Address	(if not already recorded in Appendix to Register Book).		

ried Afloat or in Dry Dock? Afloat Name of Dock Railway & also Destined Voyage

*UDBorDBa*      *feet; uE&B*      *feet; f*      *feet;*  
*capacity*    *tons. FPT*    *tons; APT*    *tons; MT*    *feet*    *tons.* }

Particulars of Classification (which must be inserted  
precisely as in Register Book & Supplements).

vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.

Report, No. 1760 Port Bar

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs at of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; those being detailed in the body of the report, should be summarised in the form shown below. Whenever the Rent of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on of this form. State also the dates and initials of any letters respecting this case. 4 8/7/18

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now required.	Machinery and Boiler Surveys (including date of N.B., if any).
------------------------------------------------------------------------------------------	---------------------------------------	----------------------------------------------------------------------

~~-100A1.8.17~~      -LMC  
S.S. Gms N: 1.16      m 5. 1-0

B.S. 3.1  
T.S. 1.15

Society's Freeboard (if assigned) as  
 painted on Ship and now verified } .....ft

ed: *Yes, not required* Was a damage report made by anyone else? If so, by whom? *Underwriter*

Damage. See Bergen Rpt. No. 1260.  
Damage stated to have been caused by collision with the  
Kamfford at Bergen Norske Jan 10<sup>th</sup> / 1918.  
Damage stern quarter.

[illegible]

TYPE OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
newed ... ..	2 STRN	2 CANT						
removed and Faird or Repaired ... ..			✓	✓		✓	✓	2nd layer of rep. work.
retired or Repaired in place ... ..	1x3 STRN	3 CANT			3 CANT			

[illegible]

*General Observations, Opinion as to Class, Recommendation, &c.:*—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptnD11, &c."

This vessel as far as seen is in good & efficient condition & eligible in my opinion to remain as classed without fresh record of survey

Survey Fee (per Section 23) ..... £

Special Damage or Repair Fee (if any) ..... £  
(per Sec. 22)

Travelling Expenses (if chargeable) ..... £

Second Surveyor's Fee (if any) £

Committee's Minute ✓ FEB. 15 FEB. 1918

*Character Assigned*

Fees applied for,

11/2/18

Received by me,

19-2 19 18

Surveyor to Lloyd's Register of British & Foreign Shipping

W 864-0063



S. S. HARROGATE

Samaji repairs cont:-

waterway angle fixed in place.

Fivebed restored + stool removed fixed + refitted

Hand rails & stanchions repaired as found necessary.

1 length prop margin plank reviewed

12 Gun platform station renewal

Prop deep reworked as found necessary

3 cent Blams paired in place & 3 back E's removed & paired

2 cant frames renewed + 3 faired in place.

Stem light bracket repaired & electric wires put

in order

all broken or disturbed cement made good

F. C. Smith

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

## ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.			WEIGHT REQUIRED by TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.			
	1st Bower ...													If Patent state name of Patentee.		
	2nd „															
	3rd „															
	Collective Weight. .															
	Stream .....															
	Kedge.....															

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

Iron Stream Chain }  
or Steel Wire.... }

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

21