

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 28. 8. 14 Port of Grimsey
No. in Reg. Book 497 Survey held at Grimsey Date, First Survey and Last Survey 26. 8. 1914

On the Wood, Iron or Steel S.S. YL. "KING CHARLES" Master
TONNAGE: GROSS 163 Built at Grimsey By whom Schofield, Hagerup & Doughty When 1901
UNDER DECK 157 Owners Consolidated S. P. & J. B. Co. (J. D. Marsden Mgr) Port belonging to Grimsey
NET 74 Owners' Address

Surveyed Afloat or in Dry Dock? yes Name of Dock Fish Destined Voyage Fishing
WB=CellDBorDBa feet; u.E&B feet; f feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
Last Report, No. 9075 Port Gms.
CHARACTER: 1-100A1 Machinery and Boiler Surveys (including date of N.R., if any): 1-L.M.C.8.13
Stm Stawler
8.13
P.S. Gms No 3. 8.13 8.12
Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition
How Done: Vessel placed in dry dock; Bottom cleaned, examined, and recoated.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Decks <u>good</u>	Inner Bottom Plating	Engine Room Skylights <u>good</u>	When put on, Month Year
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats <u>good</u>
Waterways	State if Tanks now tested	Scuppers	Masts, Yards, &c.
Coamings	Bulkheads	Cargo Hatchways	Condition, how ascertained <u>Iron OK</u>
Beams & Fastenings	Ceiling	Hatches	(State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	Sails
Caulking of ditto	Rudder <u>good</u>	Caulking ditto	Equipment letter
Rivets	Steering gear and its connections	Treenails ditto	Anchors, No. of <u>2 B. 1 K.</u>
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Cables (State if now ranged)
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	length size (on board)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	Rule length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawser & Warps
Floors		Stringers, Clamps & Shelves ditto	Standing & Running Rigging <u>good</u>
Keelsons		Salking ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptND11, &c."
This vessel is eligible, in my opinion, to remain as classed, and to have fresh record of Survey 8.14.

Survey Fee (per Section 88)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 89)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

G. J. Johnson
Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute TUE. SEP. 1-1914
Character Assigned Stm Stawler P.S. 14.



W869-0010