

1m2.15.

Received by Chief Ship Surveyor 11.6.15

Received from Chief Ship Surveyor

VESSEL'S NAME Sheuss King Albert

Rpt. h

No. 67624

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/3/92.)

Nature of Survey

DAMAGE.

Damage through

Heavy weather

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

a Bow anchor & 120 fms of chain cable
of proper weight & size steel supplied

It is submitted the vessel is worthy to remain as classed without
record of Survey as recommended

FEF. 88.2.0.

Surveyor to Lloyd's Register of Shipping



© 2020

W869-048

Lloyd's Register Foundation

1 assigned) as
now verified }

r this purpos

port att

lower

bars

120 fms

or Y.M. of Wood Ve
late if on Felt.)
en put on, Month

Yards, &c.

on, how ascertained

te if wedges remon

ent letter

1, No. of

State if now rang

ngth

(on board)

rule length

& Warps

g & Running Rigging

a Register Book con

is classed and to h

Lloyd's Register

Foundation