

m, 11, 30.

23 FEB 1940

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

ESSEL'S NAME "TASSO". Rpt. Hul. No 50509

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Hull Surveyors report the vessel placed in drydock, the bottom coated, and on account of damage through collision, 3 shell plates and 2 deck plates renewed. Repairs to shell plating, framing, bulwarks, etc. carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 2-40.

100AI
With Freeboard.
2-40 Hul.

22. 2. 40



© 2019

Lloyd's Register Foundation

W87-0095

Frames (112 Hull) good	Have pumps been examined and found effi-	Hatches good	Condition, how (State if)
			Equipment let