

# Lloyd's Register of Shipping.

TELEGRAPHIC ADDRESSES:  
INLAND - "LYKIARDOS, FEN, LONDON."  
FOREIGN - "LYKIARDOS, LONDON."  
TELEPHONE NO. 6174 AVENUE.

117/118, LEADENHALL STREET,

LYKIARDOPULO & CO.

CODES USED  
WATKINS & SCOTTS 10TH

LLOYD'S REGISTER,  
LONDON.

RECD 3 NOV 1917

ANS

London, 2ND, Nov. 1917.  
E.C. 3.

P. N. LYKIARDOPULO GREEK SUBJECT.  
G. N. LYKIARDOPULO GREEK SUBJECT.

SS/R 2

The Secretary

Lloyd's Register of Shipping

71 Fenchurch Street

E. C.

Dear Sir,

S.S. "GERASIMOS"

We are in receipt of your favour of yesterday. (H), and in reply beg to acquaint you that this steamer is on passage to Marseille, and that we have already given the necessary instructions to our agent at Marseille to do his utmost for securing a drydock for this steamer after completion of her discharge. We have also given the necessary instructions to the Captain, on behalf of the Owner, to call in your surveyor whilst steamer is in drydock, and examine bottom, rudder and all sea connections including the tail-end-shaft.

We might mention that we do not anticipate any trouble and as regards the tail-end-shaft, please note that there is not a spare on board steamer in case the one in use is found defective and has to be replaced, but we do not expect this

-1-

ment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

N.B.—This certificate has been issued in the French language on the reverse side of the original.

inging to A

ed Voyage

of Classification  
as in Register

TER.  
i Survey.  
vey and of  
Surveys.

: 3-17

7

tee.

ow

ion,

17.

length.....  
(on to  
Rule leng  
ser & War  
ding & Run

vessel in the Regis  
to remain as class



# Lloyd's Register of Shipping.

## COPY

GIARDOPULO & CO.

Lloyd's Register of Shipping


CONTINUATION SHEET No

2

necessity will arise, because the present shaft was specially built, and owing to this fact, the builders of the steamer did not think it was necessary to put a spare on board.

We shall therefore be glad if you will advise your Marseille surveyor accordingly, also ask him to pass as many parts of the ship as he possibly can without causing any delay to the steamer, and considering her age and the care that has been taken to keep her in perfect condition, we believe that the whole survey can be passed without any delay whatever.

Yours faithfully,



© 2020

Lloyd's Register  
Foundation

ment, default, or negligence of the Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of

N.B.—This certificate has been issued in the French language on the reverse side of the original.

vessel in the R  
to remain as c



Referred to the Chief Ship Surveyor  
and the Chief Engineer Surveyor.

7AM

NOV -3 1917

Also for Mr. S. A. Hill to note.

8

Shipping to register a' byoll

Ylloboqa aw jznu jnawq ent saunood , shins lltw yllnsoon  
tawmaga ent to etobllnd ent . jont slnt of pntwo dne . jllud  
broad no etaga a jup of Yllnsoon aw jll klnnt jnn dln  
tuoq saivth lltw noy jll lalt ad etolotont lltnde ew  
yuan aw saeq of mlt dw sale . Yllnllllooon toytvttne alllertan  
ylob ynn pntuaw jnawltw noo Ylllloboq ent aw qlns ent to eteq  
ent jent eteo ent dne aga tnt pntobllenco dne . tawmaga ent of  
jant etalled ew . nolltllenco jootred nll tnt qent of nakt need  
paw jentaw ylob ynn jnawltw basag ed aw yavttne olaw ent  
Yllnllllool etuoq

© 2020

Lloyd's Register  
Foundation