

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

Oct. 2

When handed in at Local Office

Oct 2

Port of

Marseilles

in
Book.

Survey held at

Marseilles

Date, First Survey

30th Aug

Last Survey

30th Aug

1917

on the ~~Wood, Iron or Steel~~

S/S. Gerasimos

Master S. Chelms

TONNAGE:-

Built at

Glasgow

By whom

Napier & Miller, Ltd

When

1913

6

ROSS 3845

Owners

N. D. Lykiardopoulos

Port belonging to

Argostoli

UNDER DK 3635

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

B=CellDBorDBa

feet; u&B

feet; f

feet; f

al capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
Assigned
expired.Machinery and Boiler
Survey
(including date of N.B., if any).

+ 100A.1: 3-17

+ LMC: 6-13

TS 6-15

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4586

Port

Msl

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Not required. Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

Slight Plinian damage

Now done:- Examined slight indentation of Bridge side plate Starboard Side. This in our opinion does not effect the efficiency of the Vessel & can be repaired at owners convenience

ARY OF DAMAGE REPAIRS:-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed	✓	✓	✓	✓	✓	✓	✓	✓
Removed and Fair'd or Repaired	✓	✓	✓	✓	✓	✓	✓	✓
Fair'd or Repaired in place	✓	✓	✓	✓	✓	✓	✓	✓

ENT CONDITION OF THE

Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
State if Tanks now tested	Scuppers	Boats
Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Ceiling	Hatches	Condition, how ascertained
Cement or Asphalt (State which)	Planking of Wood Vessels	(State if wedges removed)
Studder	Caulking ditto	Sails
Steering gear and its connections	Treenails ditto	Equipment letter
Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	„ Rule length size
	Stringers, Clamps & Shells ditto	Hawser & Warps
	Salting ditto	Standing & Running Rigging
	(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This Vessel is now in good and efficient condition and eligible to remain as classed Subject to permanent repairs at owners earliest convenience

J. Esquerre

A.P. Jones

Survey Fee (per Section 28) £ 60 : 00

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

10th Sept 1917

Received by me,

10th Sept 1917

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation

W874-0061